



Remove the RED tubing from the RO Manifold and replace it with the New Flow Restrictor tubing supplied.

MAKE SURE NOT TO CUT THE FLOW RESTRICTOR SIDE END ON THE TUBING

